

Instruction for applying the REPAIR PATCH tape



Instructions:

1. Using a cutter, we remove the damaged part.
2. Degrease the surface with the help of a suitable solvent.
3. Remove all contamination and provide appropriate roughness with the help of a wire brush.
4. Heat the damaged surface with a hot torch.
5. Using the flame of a torch, heat the mastic filler and the surface simultaneously.
 - Note: To prevent damage to the remaining coating, please avoid moving the torch.
6. Melt the mastic filler until the damaged surface is completely be filled and the molten material should be above the surface and finally, we heat the entire molten surface. Continue to cover.
7. Cut the required amount of patch from the ripper (ten centimeters more than the damaged surface).
8. We cut the corners of the cut part.
9. Smooth the molten surface with a spatula.
10. Heat the NIAKIMYA repair patch from the inside until it becomes completely shiny.
11. Place the repair patch on the damaged area before the temperature of the previously heated damaged area drops.
12. Finally, gently roll it over with a roller, taking care not to stretch the tape.

Shelf Life and Storage

Shelf Life: 2 years when stored under recommended conditions.

Storage Recommendations

- Store in a clean, dry, and well-ventilated environment.
- Keep products in their original packaging until use.
- Protect from direct sunlight, rain, snow, dust, and other environmental contaminants.
- Avoid prolonged exposure to temperatures above 40°C (104°F) or below -20°C (-4°F).
- Installation should be carried out in accordance with applicable health, safety, and environmental regulations.